



FIAT Bravo Bravo 1.4 T-JET 16V

VIN NO ZFA19800004344306

Registration Number 0004344306



MOT Date

2026-05-01

Last Service

2023-03-01

Number of Owners

2

Last Service Mileage

183322

Number of Keys

2

First Registration Date

2011-10-28

Odometer Reading

199400 km

Country First Registered

Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20250911122002
Inspection Date / Place	2025-09-11 / BCA Oberndorf	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1368
Engine Size	1.4	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	146
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Bluetooth telephone interface	Remote adjusting wing mirrors
Satellite navigation	Stability control	Central locking	Radio
Airbag Status	Anti-lock braking	Front fog lamps	Remote central locking
Split folding rear seats	CD Player	Leather steering wheel	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	No

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

15 Schäden



1 Schäden



Component		Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Hood	Paint / Scratch / Scuff	
4	Fender / Front Left	Paint / Scratch / Line	
5	Rocker Panel / Center Left	Paint / Scratch / Line	
6	Door / Front Left	Paint / Scratch / Line	
7	Sun Visor / Front Right	Interior / Loose	
8	Fender / Back Left	Bodywork / Dent / Dent	
9	Bumper / Back	Bodywork / Dent / Dent	
10	Tailgate	Paint / Scratch / Line	
11	Fender / Back Right	Bodywork / Dent / Dent	
12	Door / Front Right	Bodywork / Dent / Dent	

13	Fender / Front Right	Bodywork / Dent / Dent
14	Rocker Panel / Center Right	Paint / Scratch / Line
15	Rim / Back Left	Out of Bodywork / Scratch
16	Back Light / Left	Glass Break / Impact



1. Bumper / Front
Paint / Scratch / Scuff -



2. Bumper / Front
Paint / Scratch / Scuff -



3. Hood
Paint / Scratch / Scuff -



4. Fender / Front Left
Paint / Scratch / Line -




5. Rocker Panel / Center Left
Paint / Scratch / Line -



6. Door / Front Left
Paint / Scratch / Line -




7. Sun Visor / Front Right
Interior / Loose -



8. Fender / Back Left
Bodywork / Dent / Dent -



9. Bumper / Back
Bodywork / Dent / Dent -



10. Tailgate
Paint / Scratch / Line -



11. Fender / Back Right
Bodywork / Dent / Dent -



12. Door / Front Right
Bodywork / Dent / Dent -




13. Fender / Front Right
Bodywork / Dent / Dent -



14. Rocker Panel / Center Right
Paint / Scratch / Line -



15. Rim / Back Left
Out of Bodywork / Scratch -



16. Back Light / Left
Glass Break / Impact -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	⚠
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Audio Equipment	✓	AC / Heating System	✓
Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Other Equipments	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly 

Engine

Engine Noise		The Gears Scratch / Skip / Abnormal Operation	
Fume Quantity		Power Loss	

Brake

Brake System Anomaly 

Clutch

Clutch Functioning 

General

Test Driven Status Not Performed

-  **No troubles detected, good condition or correct tests, according to vehicle age and mileage**
-  **Damages or malfunction detected that requires repairs by the buyer**
-  **Not applicable**
-  **Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)