



FIAT Punto 2012 Benzina
punto 1.4 Pop S&S 5p

VIN NO ZFA19900000877958
Registration Number EW576WX



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-09-09	-	-	225748 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2012-06-01	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251003121831
Inspection Date / Place	2025-10-03 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Blue	Engine Size (cc)	1368
Engine Size	1.4	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	132

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	Yes
Manufacturer Warrenty			





Equipment


Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Power assisted steering	Digital Radio	Parcel Shef
Remote central locking	Stability control		

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	PIRELLI PIRELLI-CINTURATO P1	175/65//R15 - 84T / 3 mm
	PIRELLI PIRELLI-CINTURATO P1	175/65//R15 - 84T / 3 mm
	PIRELLI PIRELLI-CINTURATO P1	175/65//R15 - 84T / 3 mm
	PIRELLI PIRELLI-CINTURATO P1	175/65//R15 - 84T / 3 mm

25 Danni



3 Danni



5/12 - Report Number P20251003121831

13	Fender / Back Left	Bodywork / Dent
14	Fender / Back Left	Bodywork / Dent
15	Bumper / Back	Bodywork / Dent
16	Monogram/Emblem / Back Center	Bodywork / Breakage
17	Tailgate	Bodywork / Dent
18	Back Light / Right	Glass Break
19	Fender / Back Right	Bodywork / Dent
20	Door / Back Right	Paint / Scratch / Line
21	Door / Front Right	Paint / Scratch / Line
22	Door / Front Right	Paint / Scratch / Line
23	Mirror Shell / Front Right	Paint / Scratch / Line
24	Fender / Front Right	Bodywork / Dent
25	Pillar / Front Right	Bodywork / Dent
26	Roof	Bodywork / Dent
27	Roof	Bodywork / Dent / Hail Area
28	Rear Window / Back	Glass Break / Scratch



1. Dashboard / Front Interior / Warning Light ON -



2. Dashboard / Front Interior / Broken -




3. Floor Carpet Interior / Ripped -



4. Windshield / Front Glass Break / Impact -



5. Hood Paint / Chipping -



6. Bumper / Front Bodywork / Dent -



7. Front Light / Front Left
Glass Break -



8. Fender / Front Left
Bodywork / Dent -



9. Mirror Shell / Front Left
Paint / Scratch / Line -



10. Door / Front Left
Paint / Scratch / Line -



11. Door / Front Left
Bodywork / Dent -



12. Door / Back Left
Bodywork / Dent -



13. Fender / Back Left
Bodywork / Dent -



14. Fender / Back Left
Bodywork / Dent -



15. Bumper / Back
Bodywork / Dent -



16. Monogram/Emblem / Back Center
Bodywork / Breakage -



17. Tailgate
Bodywork / Dent -



18. Back Light / Right
Glass Break -



19. Fender / Back Right
Bodywork / Dent -



20. Door / Back Right
Paint / Scratch / Line -




21. Door / Front Right
Paint / Scratch / Line -



22. Door / Front Right
Paint / Scratch / Line -



23. Mirror Shell / Front Right
Paint / Scratch / Line -



24. Fender / Front Right
Bodywork / Dent -



25. Pillar / Front Right
Bodywork / Dent -



26. Roof
Bodywork / Dent -



27. Roof
Bodywork / Dent / Hail Area -



28. Rear Window / Back
Glass Break / Scratch -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	!
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	SPIA MOTORE ACCESA
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			