



FIAT Qubo Benzina

Qubo 1.4 8v natural power Dynamic 70cv E6

VIN NO ZFA22500006B06999
Registration Number FB049BX



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2023-10-02	-	-	125006 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2015-10-11	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250923155520
Inspection Date / Place	2025-09-23 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Gas	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1368
Engine Size	1.4	No of Doors	5
Body Type	MPV	Drive Train	Front
Seat Colour	Red	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	119

Prices

Reserve Price	3,200	Green	2,800
---------------	-------	-------	-------

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Power assisted steering	Digital Radio	Parcel Shef
Remote central locking	Stability control		

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Four Seasons	
	NEXEN	195/55//R16 - 91H / 1 mm
	NEXEN	195/55//R16 - 91H / 1 mm
	NEXEN	195/55//R16 - 91H / 1 mm
	NEXEN	195/55//R16 - 91H / 1 mm

25 Danni



11 Danni



5/13 - Report Number P20250923155520

13	Fender / Back Left	Bodywork / Dent	0.00
14	Bumper / Back	Bodywork / Dent	0.00
15	Tailgate	Bodywork / Dent	0.00
16	Back Light / Right	Glass Break	0.00
17	Rim / Back Right	Out of Bodywork / Scratch	0.00
18	Fender / Back Right	Bodywork / Dent	0.00
19	Door / Back Right	Paint / Scratch / Line	0.00
20	Door / Front Right	Paint / Scratch / Line	0.00
21	Mirror Glass / Front Right	Glass Break	0.00
22	Pillar / Front Right	Bodywork / Dent / Hail Area	0.00
23	Roof	Bodywork / Dent / Hail Area	0.00
24	Window Switch / Front Right	Interior / Not Working	0.00
25	Window Switch / Front Right	Interior / Not Working	0.00
26	Dashboard / Front	Interior / Scratched	0.00
27	Center Console	Interior / Worn - out	0.00
28	Seat / Front Left	Interior / Worn - out	0.00
29	Tailgate Upholstery / Back	Interior / Scratched	0.00
30	Panel Filling / Front Left	Interior / Scratched	0.00
31	Floor Carpet	Interior / Ripped	0.00
32	Steering Wheel / Front	Interior / Worn - out	0.00
33	TV DVD Screen / Front	Interior / Dysfunctional	0.00
34	Window Switch / Front Left	Interior / Dysfunctional	0.00
35	Antenna Base	Bodywork / Breakage	0.00
36	Antenna Rod	Missing Part	0.00
Net Total			0.00 €



1. Mirror Shell / Front Right
Paint / Scratch / Line -
0.00



2. Rim / Front Right
Out of Bodywork / Scratch -
0.00



3. Fender / Front Right
Bodywork / Dent -
0.00



4. Windshield / Front
Glass Break / Impact -
0.00



5. Hood
Bodywork / Dent / Hail Area -
0.00



6. Bumper / Front
Bodywork / Dent -
0.00



7. Bumper / Front
Bodywork / Dent -
0.00



8. Rim / Front Left
Out of Bodywork / Scratch -
0.00



9. Fender / Front Left
Bodywork / Dent -
0.00



10. Door / Front Left
Bodywork / Dent -
0.00



11. Door / Back Left
Paint / Scratch / Line -
0.00



12. Rim / Back Left
Out of Bodywork / Scratch -
0.00



13. Fender / Back Left
Bodywork / Dent -
0.00



14. Bumper / Back
Bodywork / Dent -
0.00



15. Tailgate
Bodywork / Dent -
0.00



16. Back Light / Right
Glass Break -
0.00



17. Rim / Back Right
Out of Bodywork / Scratch -
0.00




18. Fender / Back Right
Bodywork / Dent -
0.00




19. Door / Back Right
Paint / Scratch / Line -
0.00




20. Door / Front Right
Paint / Scratch / Line -
0.00



21. Mirror Glass / Front Right
Glass Break -
0.00



22. Pillar / Front Right
Bodywork / Dent / Hail Area -
0.00



23. Roof
Bodywork / Dent / Hail Area -
0.00



24. Window Switch / Front Right
Interior / Not Working -
0.00



25. Window Switch / Front Right
Interior / Not Working -
0.00



26. Dashboard / Front
Interior / Scratched -
0.00



27. Center Console
Interior / Worn - out -
0.00



28. Seat / Front Left
Interior / Worn - out -
0.00



29. Tailgate Upholstery / Back
Interior / Scratched -
0.00



30. Panel Filling / Front Left
Interior / Scratched -
0.00



31. Floor Carpet
Interior / Ripped -
0.00



32. Steering Wheel / Front
Interior / Worn - out -
0.00



33. TV DVD Screen / Front
Interior / Dysfunctional -
0.00



34. Window Switch / Front Left
Interior / Dysfunctional -
0.00



35. Antenna Base
Bodywork / Breakage -
0.00



36. Antenna Rod
Missing Part -
0.00

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Steering	!	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	!		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			