



FIAT DUCATO (30)
DUCATO TOLE 3.5 M H2 2.0 MJT 115 EURO
6 PACK

VIN NO ZFA25000002E05924

Registration Number EM216FG



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250825081636
Inspection Date / Place	2025-08-25 / BCA GARONS	Cosmetic Grade	9

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Yellow	Engine Size (cc)	1956
Engine Size	2.0	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment


Central locking	Power assisted steering	Radio
-----------------	-------------------------	-------

Equipment Details


Seat Heating	No	Air Conditioning	No
--------------	----	------------------	----

Cosmetic Damage

25 Dommages



2 Dommages



Component		Damage	Comments
1	Side Panel / Back Left	Bodywork / Dent / Deformation	
2	Side Panel / Back Left	Bodywork / Dent / Deformation	
3	Side Panel / Back Left	Bodywork / Dent / Deformation	
4	Side Panel / Back Left	Bodywork / Dent / Deformation	
5	Side Panel / Back Left	Bodywork / Dent / Deformation	
6	Side Panel / Back Left	Bodywork / Dent / Deformation	
7	Back Light / Right	Glass Break	
8	Side Panel / Back Right	Missing Part	
9	Side Panel / Back Right	Bodywork / Dent / Deformation	
10	Door / Back Right	Bodywork / Dent / Deformation	
11	Side Panel / Back Right	Bodywork / Dent / Deformation	
12	Rocker Panel / Center Right	Bodywork / Dent / Deformation	
13	Door / Front Right	Bodywork / Dent / Deformation	

14	Door / Front Right	Bodywork / Dent / Deformation
15	Mirror / Front Right	Bodywork / Breakage / Crack
16	Hubcap / Front Right	Missing element hubcap
17	Fender / Front Right	Bodywork / Dent / Deformation
18	Shield / Front	Paint / Scratch / Line
19	Mirror / Front Right	Bodywork / Breakage / Crack
20	Shield / Front	Paint / Scratch / Line
21	Fender / Front Left	Bodywork / Dent / Deformation
22	Door / Front Left	Bodywork / Dent / Deformation
23	Door / Front Left	Bodywork / Dent / Deformation
24	Door / Front Left	Bodywork / Dent / Deformation
25	Door / Front Left	Bodywork / Dent / Deformation
26	Steering Wheel / Front	Interior / Broken
27	Seat Cushion / Front Left	Interior / Dirty




1. Side Panel / Back Left
Bodywork / Dent / Deformation -



2. Side Panel / Back Left
Bodywork / Dent / Deformation -



3. Side Panel / Back Left
Bodywork / Dent / Deformation -



4. Side Panel / Back Left
Bodywork / Dent / Deformation -



5. Side Panel / Back Left
Bodywork / Dent / Deformation -




6. Side Panel / Back Left
Bodywork / Dent / Deformation -




7. Back Light / Right
Glass Break -



8. Side Panel / Back Right
Missing Part -



9. Side Panel / Back Right
Bodywork / Dent / Deformation -



10. Door / Back Right
Bodywork / Dent / Deformation -




11. Side Panel / Back Right
Bodywork / Dent / Deformation -



12. Rocker Panel / Center Right
Bodywork / Dent / Deformation -



13. Door / Front Right
Bodywork / Dent / Deformation -



14. Door / Front Right
Bodywork / Dent / Deformation -



15. Mirror / Front Right
Bodywork / Breakage / Crack -



16. Hubcap / Front Right
Missing element hubcap -



17. Fender / Front Right
Bodywork / Dent / Deformation -




18. Shield / Front
Paint / Scratch / Line -



19. Mirror / Front Right
Bodywork / Breakage / Crack -



20. Shield / Front
Paint / Scratch / Line -




21. Fender / Front Left
Bodywork / Dent / Deformation -



22. Door / Front Left
Bodywork / Dent / Deformation -



23. Door / Front Left
Bodywork / Dent / Deformation -




24. Door / Front Left
Bodywork / Dent / Deformation -



25. Door / Front Left
Bodywork / Dent / Deformation -



26. Steering Wheel / Front
Interior / Broken -



27. Seat Cushion / Front Left
Interior / Dirty -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.