



FIAT Doblò Cargo II Diesel
1.6 mjt 16v 105cv chassis E6

VIN NO ZFA26300006L27895
Registration Number FR443RV



MOT Date

2024-08-09

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2018-07-11

Odometer Reading

130412 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250722141442
Inspection Date / Place	2025-07-22 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Orange	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	2
Body Type	Box Wagon	Drive Train	Front
Seat Colour	Black	No of Seats	2
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Digital Radio	Trip Computer	Power assisted steering
Remote central locking	Stability control		

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	AVON	195/60//R16 - 97H / 2 mm
	AVON	195/60//R16 - 97H / 2 mm
	AVON	195/60//R16 - 97H / 4 mm
	AVON	195/60//R16 - 97H / 4 mm

20 Danni



10 Danni



5/12 - Report Number P20250722141442

14	Fender / Back Left	Bodywork / Dent	
15	Rocker Panel / Center Left	Bodywork / Dent	
16	Reflector / Back Right	Missing Part	
17	Bumper / Back	Bodywork / Dent	
18	Trunk Tailgate Handle / Back	Bodywork / Breakage	NON SI APRE
19	Tailgate light	Bodywork / Breakage	
20	Back Light / Left	Glass Break	
21	Fender / Back Right	Bodywork / Dent	
22	Door / Back Right	Bodywork / Dent	
23	Rocker Panel / Center Right	Bodywork / Dent	
24	Door / Front Right	Bodywork / Dent	
25	Cabin	Interior / Broken	
26	Cabin	Interior / Broken	
27	Cabin	Interior / Dented	
28	Mirror Shell / Front Right	Paint / Scratch / Line	
29	Fender / Front Right	Bodywork / Poor Previous Repair	
30	Roof	Bodywork / Dent	




1. Steering Wheel / Front Interior / Broken -



2. Panel Filling / Front Left Interior / Broken -



3. TV DVD Screen / Front Interior / Broken -



4. Floor Carpet Interior / Ripped -




6. Seat Cushion / Front Left Interior / Ripped -




7. Seat Cushion / Front Left Interior / Ripped -



8. Cabin
Interior / Dirty -



9. Windshield / Front
Glass Break -



10. Hood
Bodywork / Dent -




11. Bumper / Front
Bodywork / Breakage -



12. Fender / Front Left
Bodywork / Dent -



13. Door / Front Left
Bodywork / Dent -



14. Fender / Back Left
Bodywork / Dent -



15. Rocker Panel / Center Left
Bodywork / Dent -




16. Reflector / Back Right
Missing Part -




17. Bumper / Back
Bodywork / Dent -



19. Tailgate light
Bodywork / Breakage -




20. Back Light / Left
Glass Break -




21. Fender / Back Right
Bodywork / Dent -



22. Door / Back Right
Bodywork / Dent -



23. Rocker Panel / Center Right
Bodywork / Dent -



24. Door / Front Right
Bodywork / Dent -



25. Cabin
Interior / Broken -




26. Cabin
Interior / Broken -




27. Cabin
Interior / Dented -



28. Mirror Shell / Front Right
Paint / Scratch / Line -



29. Fender / Front Right
Bodywork / Poor Previous Repair -



30. Roof
Bodywork / Dent -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Steering	!	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	BATTERY KO.
Equipments Test			
Steering Noise / Anomaly	!		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			