



FIAT Panda 2012 Benzina
panda 1.2 Lounge easypower Gpl 69cv

VIN NO ZFA31200003081850
Registration Number EP394XX



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-04-30	-	-	173920 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-04-30	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002110631
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	LPG	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1242
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Blue	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	107

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Parcel Shef	Trip Computer
Stability control	Power assisted steering	Digital Radio	Remote central locking
Tyre Mobility Kit			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons	
	UNIROYAL UNIROYAL-ALLSEASONEXPERT 2	175/65//R14 - 82T / 4 mm
	UNIROYAL UNIROYAL-ALLSEASONEXPERT 2	175/65//R14 - 82T / 4 mm
	UNIROYAL UNIROYAL-ALLSEASONEXPERT 2	175/65//R14 - 82T / 4 mm
	UNIROYAL UNIROYAL-ALLSEASONEXPERT 2	175/65//R14 - 82T / 4 mm

Cosmetic Damage

29 Danni



9 Danni



Component		Damage	Comments
1	Steering Wheel / Front	Interior / Broken	
2	Panel Filling / Front Left	Interior / Burn	
3	Panel Filling / Front Left	Interior / Burn	
4	Panel Filling / Front Left	Interior / Broken	
5	Panel Filling / Front Right	Interior / Broken	
6	Panel Filling / Front Right	Interior / Broken	
7	Gear Knob	Interior / Ripped	
8	Seat Cushion / Front Left	Interior / Burn	
9	Floor Carpet	Interior / Broken	
10	Windshield / Front	Glass Break	
11	Hood	Bodywork / Dent	
12	Hood	Bodywork / Dent	

13	Bumper / Front	Bodywork / Dent
14	Rim / Front Left	Out of Bodywork / Scratch
15	Fender / Front Left	Bodywork / Dent
16	Mirror Shell / Front Left	Bodywork / Breakage
17	Door / Front Left	Bodywork / Dent
18	Door / Front Left	Paint / Scratch / Line
19	Door / Back Left	Bodywork / Dent
20	Door / Back Left	Bodywork / Dent
21	Fender / Back Left	Bodywork / Dent
22	Rim / Back Left	Out of Bodywork / Scratch
23	Pillar / Front Left	Bodywork / Dent / Hail Area
24	Bumper / Back	Bodywork / Dent
25	Tailgate	Paint / Scratch / Line
26	Tailgate	Bodywork / Poor Previous Repair
27	Fender / Back Right	Bodywork / Dent
28	Rim / Back Right	Out of Bodywork / Scratch
29	Door / Back Right	Bodywork / Dent
30	Door / Back Right	Bodywork / Dent
31	Door / Back Right	Paint / Scratch / Line
32	Door / Front Right	Bodywork / Dent
33	Rocker Panel / Center Right	Bodywork / Dent
34	Fender / Front Right	Bodywork / Dent
35	Rim / Front Right	Out of Bodywork / Scratch
36	Pillar / Front Right	Bodywork / Dent
37	Roof	Bodywork / Dent / Hail Area
38	Rocker Panel / Center Left	Bodywork / Dent



1. Steering Wheel / Front Interior / Broken -



2. Panel Filling / Front Left Interior / Burn -



3. Panel Filling / Front Left Interior / Burn -




4. Panel Filling / Front Left Interior / Broken -



5. Panel Filling / Front Right Interior / Broken -



6. Panel Filling / Front Right Interior / Broken -



7. Gear Knob
Interior / Ripped -



8. Seat Cushion / Front Left
Interior / Burn -



9. Floor Carpet
Interior / Broken -



10. Windshield / Front
Glass Break -



11. Hood
Bodywork / Dent -



12. Hood
Bodywork / Dent -



13. Bumper / Front
Bodywork / Dent -



14. Rim / Front Left
Out of Bodywork / Scratch -



15. Fender / Front Left
Bodywork / Dent -



16. Mirror Shell / Front Left
Bodywork / Breakage -



17. Door / Front Left
Bodywork / Dent -



18. Door / Front Left
Paint / Scratch / Line -



19. Door / Back Left
Bodywork / Dent -



20. Door / Back Left
Bodywork / Dent -



21. Fender / Back Left
Bodywork / Dent -




22. Rim / Back Left
Out of Bodywork / Scratch -



23. Pillar / Front Left
Bodywork / Dent / Hail Area -




24. Bumper / Back
Bodywork / Dent -



25. Tailgate
Paint / Scratch / Line -




26. Tailgate
Bodywork / Poor Previous Repair -




27. Fender / Back Right
Bodywork / Dent -



28. Rim / Back Right
Out of Bodywork / Scratch -



29. Door / Back Right
Bodywork / Dent -




30. Door / Back Right
Bodywork / Dent -



31. Door / Back Right
Paint / Scratch / Line -




32. Door / Front Right
Bodywork / Dent -



33. Rocker Panel / Center Right
Bodywork / Dent -



34. Fender / Front Right
Bodywork / Dent -




35. Rim / Front Right
Out of Bodywork / Scratch -



36. Pillar / Front Right
Bodywork / Dent -



37. Roof
Bodywork / Dent / Hail Area -



38. Rocker Panel / Center Left
Bodywork / Dent -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			