



FIAT Panda 2012 Diesel panda 1.3 mjt 16v 4x4 75cv

VIN NO ZFA31200003227233
Registration Number ET731HP



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2023-10-17	-	-	154051 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-06-01	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250925123338
Inspection Date / Place	2025-09-25 / BCA Lodi	Cosmetic Grade	5



Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1248
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	All-Wheel-Drive
Seat Colour	Grey	No of Seats	4
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	125

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	Yes
Manufacturer Warrenty			







Equipment

Central locking	Alloys wheels	Parcel Shef	Remote central locking
Tyre Mobility Kit	Power assisted steering	Digital Radio	Remote adjusting wing mirrors
Trip Computer	Stability control		


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons	
	NOKIAN NOKIAN-SEASONPROOF	175/65//R15 - 88H / 2 mm
	NOKIAN NOKIAN-SEASONPROOF	175/65//R15 - 88H / 2 mm
	NOKIAN NOKIAN-SEASONPROOF	175/65//R15 - 88H / 3 mm
	NOKIAN NOKIAN-SEASONPROOF	175/65//R15 - 88H / 3 mm

Cosmetic Damage

23 Danni



5 Danni



Component		Damage	Comments
1	Floor Carpet	Interior / Ripped	
2	Panel Filling / Front Left	Interior / Broken	
3	Panel Filling / Front Right	Interior / Broken	
4	Steering Wheel / Front	Interior / Worn - out	
5	Seat / Front Left	Interior / Ripped	
6	Windshield / Front	Glass Break / Impact	
7	Hood	Bodywork / Dent / Hail Area	
8	Bumper / Front	Bodywork / Breakage	
9	Bumper / Front	Bodywork / Dent	
10	Rim / Front Left	Out of Bodywork / Scratch	
11	Fender / Front Left	Bodywork / Dent	
12	Mirror Shell / Front Left	Paint / Scratch / Line	

13	Door / Front Left	Bodywork / Dent
14	Door / Back Left	Bodywork / Poor Previous Repair
15	Fender / Back Left	Bodywork / Dent
16	Rim / Back Left	Out of Bodywork / Scratch
17	Pillar / Front Left	Bodywork / Dent / Hail Area
18	Bumper / Back	Bodywork / Dent
19	Tailgate	Bodywork / Dent
20	Fender / Back Right	Bodywork / Poor Previous Repair
21	Rim / Back Right	Out of Bodywork / Scratch
22	Door / Back Right	Bodywork / Dent
23	Door / Front Right	Bodywork / Dent
24	Mirror Shell / Front Right	Paint / Scratch / Line
25	Fender / Front Right	Bodywork / Dent
26	Fender / Front Right	Bodywork / Dent
27	Rim / Front Right	Out of Bodywork / Scratch
28	Roof	Bodywork / Dent / Hail Area



1. Floor Carpet
Interior / Ripped -



2. Panel Filling / Front Left
Interior / Broken -




3. Panel Filling / Front Right
Interior / Broken -



4. Steering Wheel / Front
Interior / Worn - out -



5. Seat / Front Left
Interior / Ripped -



6. Windshield / Front
Glass Break / Impact -



7. Hood
Bodywork / Dent / Hail Area -



8. Bumper / Front
Bodywork / Breakage -



9. Bumper / Front
Bodywork / Dent -



10. Rim / Front Left
Out of Bodywork / Scratch -




11. Fender / Front Left
Bodywork / Dent -




12. Mirror Shell / Front Left
Paint / Scratch / Line -



13. Door / Front Left
Bodywork / Dent -




14. Door / Back Left
Bodywork / Poor Previous Repair -



15. Fender / Back Left
Bodywork / Dent -



16. Rim / Back Left
Out of Bodywork / Scratch -



17. Pillar / Front Left
Bodywork / Dent / Hail Area -



18. Bumper / Back
Bodywork / Dent -



19. Tailgate
Bodywork / Dent -



20. Fender / Back Right
Bodywork / Poor Previous Repair -



21. Rim / Back Right
Out of Bodywork / Scratch -



22. Door / Back Right
Bodywork / Dent -



23. Door / Front Right
Bodywork / Dent -



24. Mirror Shell / Front Right
Paint / Scratch / Line -




25. Fender / Front Right
Bodywork / Dent -



26. Fender / Front Right
Bodywork / Dent -



27. Rim / Front Right
Out of Bodywork / Scratch -



28. Roof
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested