



FIAT Panda 2012 Benzina
Panda 1.2 easypower Lounge Gpl 69cv E6

VIN NO ZFA31200003299204
Registration Number EV207EE



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-04-03	-	-	147452 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2014-04-30	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251003085629
Inspection Date / Place	2025-10-03 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	LPG	Gearbox Type	Manual
Colour	Beige	Engine Size (cc)	1242
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Beige	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	106

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Alloys wheels	Parcel Shef	Trip Computer
Stability control	Power assisted steering	Digital Radio	Remote central locking
Tyre Mobility Kit			

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Winter	
	FULDA	175/65//R14 - 82T / 3 mm
	FULDA	175/65//R14 - 82T / 3 mm
	FULDA	175/65//R14 - 82T / 3 mm
	FULDA	175/65//R14 - 82T / 3 mm

27 Danni



5 Danni




5/13 - Report Number P20251003085629


13	Fender / Front Left	Bodywork / Dent
14	Door / Front Left	Bodywork / Dent
15	Door / Back Left	Bodywork / Dent
16	Rocker Panel / Center Left	Bodywork / Dent
17	Fender / Back Left	Bodywork / Dent
18	Rim / Back Left	Out of Bodywork / Scratch
19	Bumper / Back	Bodywork / Dent
20	Tailgate	Bodywork / Dent
21	Trunk Tailgate Handle / Back	Bodywork / Breakage
22	Fender / Back Right	Bodywork / Dent
23	Fender / Back Right	Bodywork / Dent
24	Rim / Back Right	Out of Bodywork / Scratch
25	Door / Back Right	Bodywork / Dent
26	Rocker Panel / Center Right	Bodywork / Dent
27	Door Handle / Front Right	Paint / Scratch / Line
28	Door / Front Right	Bodywork / Dent
29	Mirror Shell / Front Right	Paint / Scratch / Line
30	Fender / Front Right	Bodywork / Dent
31	Roof	Bodywork / Dent
32	Front Light / Front Right	Glass Break



1. Dashboard / Front Interior / Warning Light ON -



2. Roof Upholstery Interior / Ripped -




3. Steering Wheel / Front Interior / Broken -




4. Panel Filling / Front Left Interior / Broken -



5. Floor Carpet Interior / Ripped -



6. Windshield / Front Glass Break / Impact -



7. Hood
Paint / Chipping -



8. Bumper / Front
Bodywork / Breakage -



9. Bumper / Front
Bodywork / Dent -




10. Grille / Front
Bodywork / Breakage -



11. Grille / Front
Bodywork / Breakage -



12. Rim / Front Left
Out of Bodywork / Scratch -




13. Fender / Front Left
Bodywork / Dent -




14. Door / Front Left
Bodywork / Dent -



15. Door / Back Left
Bodywork / Dent -



16. Rocker Panel / Center Left
Bodywork / Dent -



17. Fender / Back Left
Bodywork / Dent -



18. Rim / Back Left
Out of Bodywork / Scratch -



19. Bumper / Back
Bodywork / Dent -



20. Tailgate
Bodywork / Dent -



21. Trunk Tailgate Handle / Back
Bodywork / Breakage -



22. Fender / Back Right
Bodywork / Dent -




23. Fender / Back Right
Bodywork / Dent -



24. Rim / Back Right
Out of Bodywork / Scratch -



25. Door / Back Right
Bodywork / Dent -



26. Rocker Panel / Center Right
Bodywork / Dent -



27. Door Handle / Front Right
Paint / Scratch / Line -




28. Door / Front Right
Bodywork / Dent -



29. Mirror Shell / Front Right
Paint / Scratch / Line -



30. Fender / Front Right
Bodywork / Dent -



31. Roof
Bodywork / Dent -



32. Front Light / Front Right
Glass Break -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	⚠		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	SPIA MOTORE ACCESA
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	⚠
Engine Noise	⚠		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
⚠ Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			