



FIAT 500 Benzina
500 1.2 Lounge 69cv

VIN NO ZFA3120000J024748
Registration Number EW893GB



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-06-17	-	-	111990 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-06-01	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002163559
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1242
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour	Beige	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Sunroof	Parcel Shef
Remote central locking	Tyre Mobility Kit	Power assisted steering	Digital Radio
Volante multifuncion	Remote adjusting wing mirrors	Trip Computer	Stability control


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons	
	LASSA	185/55//R15 - 82V / 3 mm
	LASSA	185/55//R15 - 82V / 3 mm
	LASSA	185/55//R15 - 82V / 3 mm
	LASSA	185/55//R15 - 82V / 3 mm

Cosmetic Damage

23 Danni



6 Danni



Component		Damage	Comments
1	Dashboard / Front	Interior / Broken	
2	Floor Carpet	Interior / Ripped	
3	Dashboard / Front	Interior / Scratched	
4	Seat / Back Left	Interior / Burn	
5	Seat / Back Left	Interior / Burn	
6	Windshield / Front	Glass Break / Impact	
7	Hood	Bodywork / Dent	
8	Bumper / Front	Bodywork / Dent	
9	Monogram/Emblem / Front Center	Missing Part	
10	Fender / Front Left	Bodywork / Dent	
11	Rim / Front Left	Out of Bodywork / Scratch	
12	Mirror Shell / Front Left	Paint / Scratch / Line	

13	Door / Front Left	Bodywork / Dent
14	Fender / Back Left	Bodywork / Dent
15	Rim / Back Left	Out of Bodywork / Scratch
16	Pillar / Front Left	Bodywork / Dent / Hail Area
17	Bumper / Back	Bodywork / Breakage
18	Back Light / Right	Glass Break
19	Tailgate	Paint / Scratch / Line
20	Fender / Back Right	Bodywork / Dent
21	Rim / Back Right	Out of Bodywork / Scratch
22	Door / Front Right	Bodywork / Dent
23	Mirror Shell / Front Right	Paint / Scratch / Line
24	Fender / Front Right	Bodywork / Dent
25	Rocker Panel / Center Right	Bodywork / Dent
26	Pillar / Front Right	Bodywork / Dent
27	Roof	Bodywork / Dent / Hail Area
28	Panoramic Roof	Glass Break / Impact
29	Gear Knob	Interior / Ripped



1. Dashboard / Front
Interior / Broken -



2. Floor Carpet
Interior / Ripped -



3. Dashboard / Front
Interior / Scratched -



4. Seat / Back Left
Interior / Burn -



5. Seat / Back Left
Interior / Burn -



6. Windshield / Front
Glass Break / Impact -



7. Hood
Bodywork / Dent -



8. Bumper / Front
Bodywork / Dent -



9. Monogram/Emblem / Front Center
Missing Part -



10. Fender / Front Left
Bodywork / Dent -



11. Rim / Front Left
Out of Bodywork / Scratch -



12. Mirror Shell / Front Left
Paint / Scratch / Line -



13. Door / Front Left
Bodywork / Dent -




14. Fender / Back Left
Bodywork / Dent -



15. Rim / Back Left
Out of Bodywork / Scratch -



16. Pillar / Front Left
Bodywork / Dent / Hail Area -



17. Bumper / Back
Bodywork / Breakage -



18. Back Light / Right
Glass Break -



19. Tailgate
Paint / Scratch / Line -



20. Fender / Back Right
Bodywork / Dent -



21. Rim / Back Right
Out of Bodywork / Scratch -



22. Door / Front Right
Bodywork / Dent -



23. Mirror Shell / Front Right
Paint / Scratch / Line -



24. Fender / Front Right
Bodywork / Dent -




25. Rocker Panel / Center Right
Bodywork / Dent -



26. Pillar / Front Right
Bodywork / Dent -



27. Roof
Bodywork / Dent / Hail Area -



28. Panoramic Roof
Glass Break / Impact -



29. Gear Knob
Interior / Ripped -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested