



FIAT Panda III 2021

Panda 1.0 firefly hybrid City Life s&s 70cv

VIN NO ZFABF5CJ1N3J12408

Registration Number 3J12408



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2023-02-28

Odometer Reading



43385 km

Country First Registered



Spain

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250926113513
Inspection Date / Place	2025-09-26 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified
Fuel Type	Hybrid	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	89

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Rental Car	Imported	Yes
Manufacturer Warrenty			





Equipment

Central locking	Digital Radio	Remote central locking	Stability control
Power assisted steering	Parcel Shef	Trip Computer	


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm

Cosmetic Damage

15 Danni



0 Danni



Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Hood	Bodywork / Dent	
3	Bumper / Front	Bodywork / Dent	
4	Fender / Front Left	Bodywork / Dent	
5	Door / Front Left	Bodywork / Dent	
6	Door / Back Left	Bodywork / Dent	
7	Fender / Back Left	Paint / Scratch / Line	
8	Pillar / Front Left	Bodywork / Dent	
9	Bumper / Back	Bodywork / Dent	
10	Door / Back Right	Bodywork / Dent	
11	Door / Front Right	Bodywork / Dent	
12	Fender / Front Right	Bodywork / Dent	

13	Tire / Front Right	Tire
14	Pillar / Front Right	Bodywork / Dent
15	Roof	Bodywork / Dent / Hail Area



1. Windshield / Front
Glass Break / Impact -



2. Hood
Bodywork / Dent -



3. Bumper / Front
Bodywork / Dent -




4. Fender / Front Left
Bodywork / Dent -



5. Door / Front Left
Bodywork / Dent -



6. Door / Back Left
Bodywork / Dent -



7. Fender / Back Left
Paint / Scratch / Line -



8. Pillar / Front Left
Bodywork / Dent -



9. Bumper / Back
Bodywork / Dent -



10. Door / Back Right
Bodywork / Dent -



11. Door / Front Right
Bodywork / Dent -



12. Fender / Front Right
Bodywork / Dent -



13. Tire / Front Right
Tire - Replace



14. Pillar / Front Right
Bodywork / Dent -



15. Roof
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

Not tested