



LANCIA DELTA

Delta 2.0 Multijet 16v 165 DPF Platino

VIN NO ZLA84400001056382
Registration Number AS843NS



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	143380 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2010-05-21	-

Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20250915135044
Inspection Date / Place	2025-09-15 / BCA ANGOULEME	Cosmetic Grade	9

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Red	Engine Size (cc)	1956
Engine Size	2.0	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	139

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warranty			





Equipment


Central locking	Radio	Alloys wheels	Front fog lamps
Electrically adjustable seats	Rear parking sensors	Stability control	Power assisted steering

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Glass		

Cosmetic Damage

35 Dommages



18 Dommages



Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Dirty	
2	Panel Filling / Front Left	Interior / Worn - out	
3	Floor Carpet	Interior / Worn - out	
4	Floor Carpet	Interior / Dirty	
5	Steering Wheel / Front	Interior / Worn - out	
6	Steering Wheel / Front	Interior / Dirty	
7	Dashboard / Front	Interior / Worn - out	
8	Dashboard / Front	Interior / Worn - out	
9	Dashboard / Front	Interior / Dirty	
10	Panel Filling / Back Left	Interior / Worn - out	
11	Panel Filling / Back Left	Interior / Dirty	
12	Seat / Back Center	Interior / Dirty	

13	Panel Filling / Back Right	Interior / Worn - out
14	Panel Filling / Front Right	Interior / Worn - out
15	Panel Filling / Front Right	Interior / Dirty
16	Floor Carpet	Interior / Dirty
17	Seat / Front Right	Interior / Dirty
18	HandBrake Handle	Interior / Dirty
19	Corner Bumper / Front Right	Paint / Scratch / Line
20	Corner Bumper / Front Right	Bodywork / Dent / Dent
21	Corner Bumper / Front Right	Bodywork / Breakage
22	Bumper / Front	Bodywork / Breakage
23	Bumper / Front	Paint / Scratch / Scuff
24	Hood	Paint / Scratch / Scuff
25	Hood	Paint / Scratch / Line
26	Fender / Front Left	Paint / Scratch / Line
27	Fender / Front Left	Paint / Scratch / Line
28	Mirror / Front Left	Paint / Scratch / Scuff
29	Door / Front Left	Paint / Scratch / Scuff
30	Door / Front Left	Paint / Scratch / Line
31	Door / Back Left	Paint / Scratch / Line
32	Door / Back Left	Bodywork / Dent / Deformation
33	Fender / Back Left	Paint / Scratch / Line
34	Fender / Back Left	Bodywork / Dent / Deformation
35	Fender / Back Left	Bodywork / Assembly
36	Fender / Back Left	Bodywork / Breakage
37	Corner Bumper / Back Left	Paint / Scratch / Scuff
38	Corner Bumper / Back Left	Bodywork / Assembly
39	Corner Bumper / Back Right	Bodywork / Dent / Deformation
40	Corner Bumper / Back Right	Paint / Scratch / Scuff
41	Fender / Back Right	Paint / Scratch / Scuff

42	Fender / Back Right	Paint / Scratch / Scuff
43	Door / Back Right	Paint / Scratch / Scuff
44	Door / Back Right	Bodywork / Dent / Deformation
45	Door / Back Right	Paint / Scratch / Scuff
46	Fender / Back Right	Bodywork / Dent / Deformation
47	Fender / Front Right	Bodywork / Dent / Deformation
48	Fender / Front Right	Paint / Scratch / Scuff
49	Fender / Front Right	Paint / Scratch / Scuff
50	Fender / Front Right	Missing Part
51	Fender / Front Right	Bodywork / Dent / Deformation
52	Fender / Front Right	Paint / Scratch / Scuff
53	Rim / Front Right	Out of Bodywork / Breakage



1. Panel Filling / Front Left
Interior / Dirty -



2. Panel Filling / Front Left
Interior / Worn - out -



3. Floor Carpet
Interior / Worn - out -




4. Floor Carpet
Interior / Dirty -




5. Steering Wheel / Front
Interior / Worn - out -




6. Steering Wheel / Front
Interior / Dirty -




7. Dashboard / Front
Interior / Worn - out -




8. Dashboard / Front
Interior / Worn - out -



9. Dashboard / Front
Interior / Dirty -




10. Panel Filling / Back Left
Interior / Worn - out -



11. Panel Filling / Back Left
Interior / Dirty -



12. Seat / Back Center
Interior / Dirty -



13. Panel Filling / Back Right Interior / Worn - out -




14. Panel Filling / Front Right Interior / Worn - out -



15. Panel Filling / Front Right Interior / Dirty -




16. Floor Carpet Interior / Dirty -




17. Seat / Front Right Interior / Dirty -




18. HandBrake Handle Interior / Dirty -



19. Corner Bumper / Front Right
Paint / Scratch / Line -



20. Corner Bumper / Front Right
Bodywork / Dent / Dent -




21. Corner Bumper / Front Right
Bodywork / Breakage -




22. Bumper / Front
Bodywork / Breakage -



23. Bumper / Front
Paint / Scratch / Scuff -



24. Hood
Paint / Scratch / Scuff -



25. Hood
Paint / Scratch / Line -



26. Fender / Front Left
Paint / Scratch / Line -



27. Fender / Front Left
Paint / Scratch / Line -



28. Mirror / Front Left
Paint / Scratch / Scuff -



29. Door / Front Left
Paint / Scratch / Scuff -



30. Door / Front Left
Paint / Scratch / Line -



31. Door / Back Left
Paint / Scratch / Line -



32. Door / Back Left
Bodywork / Dent / Deformation -



33. Fender / Back Left
Paint / Scratch / Line -



34. Fender / Back Left
Bodywork / Dent / Deformation -



35. Fender / Back Left
Bodywork / Assembly -



36. Fender / Back Left
Bodywork / Breakage -



37. Corner Bumper / Back Left
Paint / Scratch / Scuff -



38. Corner Bumper / Back Left
Bodywork / Assembly -



39. Corner Bumper / Back Right
Bodywork / Dent / Deformation -



40. Corner Bumper / Back Right
Paint / Scratch / Scuff -



41. Fender / Back Right
Paint / Scratch / Scuff -




42. Fender / Back Right
Paint / Scratch / Scuff -



43. Door / Back Right
Paint / Scratch / Scuff -




44. Door / Back Right
Bodywork / Dent / Deformation -




45. Door / Back Right
Paint / Scratch / Scuff -



46. Fender / Back Right
Bodywork / Dent / Deformation -




47. Fender / Front Right
Bodywork / Dent / Deformation -




48. Fender / Front Right
Paint / Scratch / Scuff -




49. Fender / Front Right
Paint / Scratch / Scuff -




50. Fender / Front Right
Missing Part -



51. Fender / Front Right
Bodywork / Dent / Deformation -



52. Fender / Front Right
Paint / Scratch / Scuff -



53. Rim / Front Right
Out of Bodywork / Breakage -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.